

**THIS PAGE IS INSERTED BY OIPE SCANNING
AND IS NOT PART OF THE OFFICIAL RECORD**

Best Available Images

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

BLACK BORDERS

TEXT CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT

BLURRY OR ILLEGIBLE TEXT


SKEWED/SLANTED IMAGES

COLORED PHOTOS HAVE BEEN RENDERED INTO BLACK AND WHITE

VERY DARK BLACK AND WHITE PHOTOS

UNDECIPHERABLE GRAY SCALE DOCUMENTS

**IMAGES ARE THE BEST AVAILABLE
COPY. AS RESCANNING WILL NOT
CORRECT IMAGES, PLEASE DO NOT
REPORT THE IMAGES TO THE
PROBLEM IMAGE BOX.**



18

2

FIGURE 1




Figure 2




Figure 3




FIGURE 4A





FIGURE 4b

Figure 5a






Figure 58

146

6

154

120

156

154

ROM

118

124

122

EEPROM

CP64

LED

DRIVER

150

126

SWITCH
MATRIX

EXTERNAL
INTERFACE

152

FIGURE 6.




FIGURE 7




FIGURE 8a




FIGURE 8b




FIGURE 8C




Figure 8d




FIGURE 8e




FIGURE 9B

Figure 9B

